

Inspection No. 2986-1575

# Visual Property Inspection

7 Glenview Pl., Huntington, New York 11743

#### Prepared for :

Chris McTammany 125 Main St., Port Washington, New York 11050 Phone No. : (310) 367-9120



#### Inspected by :

Bob Van Stry 34 Metzner Rd. Ronkonkoma, New York 11779 Phone: (631) 467-8900 Fax: (631) 585-2242 Email: Bob.VanStryJr@pillartopost.com



#### **Inspection Preamble**

A visual home inspection was conducted to determine the overall condition of the home and identify areas that are outdated, in a state of disrepair or deteriorated and requiring updating, replacement, maintenance or repairs. The inspection is limited to a visual inspection that inherently has limitations with finished materials and stored items in a home.

Limitations					
✓ Parging	Debris	Snow	✓ Vegetation		
Conditions					
Clear Approx. Temper	Rain Rature 103	Frozen Ground	I		
Building					
Detached Estimated Age: 4	✓2 Story 46 yrs	Split Level House Faces: Sou	th		
The insp House lo		a colonial style home	e built around 1957. House will r	need some up	dating. Overall
Foundation			D	amaged:	No
Concrete	Block	Parging	Cracks	_	
	on cracks to reduc		some areas to help keep water a netration and subsequent damag		No
Brick	✓ Vinyl	Wood		-	
Vinyl sidi	ng looked ok.				

Siding looked ok.

THE HOME OF HOME INSPECTION <sup>33</sup> Date: 22-J	ul-2011	44	7 Glenview Pl.,, Huntington,	New York 1174
				and Exterio
Windows and Doors Updated Window Wells Upgraded windows looked c				
Landscaping	Shrub	▼ Tree		
Slopes to house Trim and maintain vegetation finishing materials.			Earth to Wood contact	re wear of
Driveway	Asphalt	Gravel	Damaged:	No
Lighting			Operational:	Yes
Receptacles         GFCI Protected       Install GFCI	No Ground	Open Ground	Operational:	Yes
Walkway/Path	Brick	Patio Block	No Visible Damage Not	ed



7 Glenview Pl.,, Huntington, New York 11743

# Property and Exterior

## Porch/Entry

Unsecured

Stone tile

Front deck looked ok. Front entrance door looked ok.

✔ Wood

Crack

No Visible Damage Noted



Old wood steps looked ok.



View under the deck. Looked ok.



Deck looked ok.



7 Glenview Pl.,, Huntington, New York 11743

## **Property and Exterior**

Deck/Patio		No Visible Dama	age Noted
Slopes to House	Improperly constructed	Composite	Concrete
May need to add more Concrete patio looked c	support to the roof above to handle he	eavy snow loads.	
Patio looked ok.			
Railing     Unsecured     Incomplete	te Vood	Dama	ged: No




Inspected By:					
Binocular	Roof Edge	Walk On	No Access		
Limitations					
Deck	Gravel Cover	Height	Rain		
Main Roof					
✓ Flat	Gable	Valley	Other		
tightly. If bu roofer chec Add some Roof looke Anticipate drainage fu component	ulge does not go d ck further. roof vents to the lo d ok. regular maintenand unction and reduce	own when roof co ower roof. ce to the roofing the potential for	e caused by extreme heat an pols, you will need to cut out surface, gutters and related leaks to develop. Gutter clo major, sometimes costly dan	t bulge and patch ro accessories to prov ogs and loose or da	oof. Have a vide intended maged
Gutter/Downs	pout			Damaged:	No
Unsecured	✓ Aluminum	Galvanized	Drains below ground		
✓ Drains above gr	ound	✓ Extend Leade	er Spill		

Gutters looked ok. Extend all downspouts minimum 6' away from foundation to reduce wall deterioration, potential water entry and subsequent damages.



Extend leader.




Roof ok.

Roof over patio.



7 Glenview Pl.,, Huntington, New York 11743

#### **Roof Structure**



Front roof.



Rolled roofing.



Life Expectancy

✓ Middle

Exceeded

End



7 Glenview Pl.,, Huntington, New York 11743

### Roof Structure

## Accessory

Unsecured

✓ Air Vent

Skylight

Visible Damage Noted

Both skylights are old. The home made old skylight has a lot of caulk on it and could be a problem in the future.

The skylight above the bathroom has a crack in it and is old. Budget to replace both skylights.

✓ Vent Stack



Old skylight.



Old skylight.

Home made skylight.




Outer covering starting to crack.

Flashing				No Visible Dam	age Noted
Concealed	✓ Chimney	Dormer	Drip Edge	Flat Roof	Skylight
✓ Roof to Wall	✓ Stack	Valley	Aluminum 🗸	🗌 Gap	Deterioration
Corrosion	Reseal	Replace Whe	en Re-roofing	Copper	
Secure stack vent flashing better.					



7 Glenview Pl.,, Huntington, New York 11743

### Roof Structure






7 Glenview Pl.,, Huntington, New York 11743

## Roof Structure

Visible Flue	Liner			Damaged:	No
None Improper inst	Metal Insert	✓ Clay ✓ Advise Clea	Rain Cap aning and Sweeping	Crack	
of heatin		eplaces. This s		es to promote safe and effici ally or as prescribed by the o	
	N/				
8251					
C.	E side	H			

Top mounted damper for fireplace.







Insulate heating pipe.

Old water stains.






Estimated Depth	5 inches				
l recomm	end adding more in	sulation to help lo	wer heating cost	. (6 - 10 ")	
anus IOC					
Ventilation					
None	✓ Soffit	Gable End	✓ Ridge	Mechanical	Blocked
l recomm	end adding ridge ve	ents to get better a	irflow in attic spa	aces.	
Exhaust Duct	:				
Concealed	Not Insulated	Into Attic	Plastic		
Bath vent	s were concealed.				



Most of the basement was finished. I did have some small areas that I could see the foundation wall and some structure.





wall behind washing machine wall.



Professional Home Inspection					<b>Van Stry</b> 000005960
THE HOME OF HOME INSPECTION	Date: 22-Jul-	2011	1/1/	7 Glenview Pl.,, Huntington, New Yo	ork 11743
				Basement/St	ructure
Ceiling Stain Un Ceiling looked ok.	finished	Drywall	✓ Drop ceiling	No Visible Damage Noted	
Circuit Wire ✓ Concealed □Ex	posed Wiring	Unsecured			
Basement Stairway				No Visible Damage Noted	
Unsecured Wo	orn	Trip Hazard	<b>✓</b> Wood	Carpet	
				s a possible trip hazard.	
Railing	complete	Wood		Damaged: No	D

Need to add a gripable handrail at the top of the stair case. Current handrail is unsafe.




16000005960

**Bob Van Stry** 

7 Glenview Pl.,, Huntington, New York 11743

#### **Basement/Structure**



Wood beam.

Professional Home Is	Ispection				<b>Bob Van Stry</b> 16000005960
THE HOME OF HOME INS	PECTION <sup>™</sup> Date: 22-Ju	1-2011	1///	7 Glenview Pl.,,	Huntington, New York 11743
					Basement/Structure
Post				No Visible Da	amage Noted
On Slab	Concealed	Adjustable	Brick	Metal	Wood
Bearing Wall Concealed				No Visible Da	amage Noted
Crawl Space	Vapor Barrier Earth Floor Vaccess crawlspace	✓ Insulated ✓ Concrete Floor . Small spot I could		Mildew Barrier Required	Stain
Bruch					

Sealed access to crawlspace.

Professional Home Inspection PILIAP TO POSt*				1	<b>Bob Van Stry</b> 16000005960
THE HOME OF HOME INSPECTIONS	Date: 22-Ju	1-2011	1////	7 Glenview Pl.,, H	untington, New York 11743
					Electrical Service
	Conduit	✓ 120/240 Volt		Frayed	Copper
	ents and up				review and provide bact safety in the home
Main Disconnect					
Switch/Cartridge Fuse Ampere Rating 100		Breaker	Overfused		
Distribution Panel Not Opened Ot Location Basement wall.	ostructed	Unsecured Ampere Rating 100	✓ Overloaded	Upgrade	
	Electrica				

Too many breakers.

Professional Home Rilar To I				<b>Van Stry</b> 00005960
THE HOME OF HOME IN	11/1	ul-2011	7 Glenview Pl.,, Huntington, New Yo	rk 11743
			Electrical S	Service
<b>Fuse</b> ✓ Breaker	Screw	GFCI Breaker	AFCI Breaker	
To many panel looi		e panel for 100 am	np service. Have an electrician check further. Otherwi	ise
Circuit Wire				
Concealed	Aluminum [] Aluminum	Copper Corrosion	Non-Metallic Sheathed	
Receptacles	and Lighting			
	exhaust fans out of and receptacles that			
Grounding				
Concealed	Ground Rod	✓ Water Main	Disconnected Meter By-Pass	
The integ	rity of the electrical	system ground car	nnot be verified by a visual inspection.	
Bonding				
Concealed Unsecured	✓ Water Pipe	Gas Pipe	Improper Connection	
Provide b	onding to gas lines	to complete groun	id system.	



Limitations		
Operating in Heating Mode	System Shut Down	Piping Concealed
Weather		
Smoke and CO Detectors		
Basement 1st Floor	2nd Floor 3rd Floo	or
required by manufacturer o operation. It is common for	r local regulations. Provide regu	etectors in the home where recommended or lar testing and maintenance to ensure proper eplacing CO detectors every 5-7 years and endations should be used as a guide.
Heating System		Operational: Yes
✓ Hot Water System	Standard Efficiency	Advise Service and Repair Contract

Hot Water System
 Gas Fired
 Manufacturer Slant Finn

This was a good cast iron boiler and it was working good at time of inspection.





## Heating

Thermostat/Hu	ımidistat			Operation	al: Yes
Unsecured	Programmable	✓ Standard	✓ Multi Zone System		
2 Zone Hea 2 Circulatin	ating. Ig pumps seen.				
Inter					
2 pumps					
Air Requireme	nt				
✓ Internal	External	Inadequate			
Venting					
Sidewall	✓ Metal	Improper Rise	Unsecured	Corrosion	Soot
Life Expectance	-				
Typical	Middle/End	Exceeded			
Unit was at	oout 11 years old.				



7 Glenview Pl.,, Huntington, New York 11743

## Heating

Gas Burner				Operatio	onal: Yes
Not Checked	Get service re	pair contract.		-	
Burners w	ere working ok at	time of inspection.			
Ignition Electronic	Pilot & Thern	nocoupl			
Heat Shield Missing Ok.	Corrosion	Soot			
AC/Heat Pum	р				Functional
Not Checked	✓ Air to Ai	✓ Though Wall	Damaged Fins	Corrosion	Dirty
Wall units	worked ok.				



## **Plumbing Components**

Limitation ✓ Finished Baseme	ent	House Winterized		
Public Supply ✓ Metered	Concealed	Copper		
	Water Main Sh yei Har	Aut for a state of the state of		
Shut-Off Valve	Corrosion	Leak		
Main water shute	DLD W	e Handle		
Hose Bibb				ot Applicable
✓ Not Checked	Frost Free	Shut-Off Valve Reca	aulk Unsecured	Corrosion
		Dage 22 of	50	2096 4



7 Glenview Pl.,, Huntington, New York 11743

#### **Plumbing Components**

## Gas Plumbing


✓ Meter Outside

Small areas I could see looked ok.









Galvanized waste pipe.

Vent Stack/P	iping			Damaged:	No	-
Concealed	Cast Iron	✓ Plastic	Undersized	Unsecured		
Main Cleanou	ut			Damaged:	No	-
Concealed	Improper Plug					
Landing Deserve	and flamm					

Location Basement floor.

Cleanout was behind the laundry room back wall. I recommend installing an access hatch to get to it. Because it is underground, I recommend having a Cesspool Company dig up cover of cesspool and determine its current location and condition.



Behind laundry room wall.



7 Glenview Pl.,, Huntington, New York 11743

## **Plumbing Components**

Hot Water Tan	k			Operational:	Yes
Power Vented	Gas	Dirty	Unsecured		
Age 6 years		Estimated Capacity	1.G. 40		
Hot water t	ank looked OK.6	o years old.			
Life Expectance	<b>∀</b> Middle	Exceeded			
Fuel Shut-Off					
Concealed					
Location At Unit					
Relief Valve					
No Test Lever	Corrosion	Other			
Discharge Tub	e				
Undersized	Discharge	Install for Safety	,		
Venting				Damaged:	No
<b>✓</b> Flue	Sidewall	Improper Rise	Unsecured	Corrosion Soot	
Burn Chamber					
✓ Not Checked	Needs Adjust	ment			



7 Glenview Pl.,, Huntington, New York 11743

## **Plumbing Components**

## Sump Pump

Not Checked Submersible
 Permanent Connection
 Suspect Installation

Standpipe
Corrosion

Float Checked	No Cover
✓ To exterior grade	

Functional

#### Part of french drain system. Looked ok.



Pump for french drain system.



7 Glenview Pl.,, Huntington, New York 11743

#### **Plumbing Components**

#### Laundry Area

▼ No Floor Drain Visible Washing Machine GE

Dryer GE

Clean exhaust vent periodically, depending on use, but at least every 2 years, or when installing your dryer in a new location.

Disconnect vent from the dryer and clean one section at a time until you reach the exhaust hood.


To clean out lint, use the hose attachment on your vacuum, or a pole or wire with a feather duster or rag attached.

Be sure the flapper on the outside end of vent moves freely.

When cleaning is complete, be sure to follow the Installation Instructions supplied with your dryer for final product check."

#### Problem with lights in laundry room. Have corrected.







7 Glenview Pl.,, Huntington, New York 11743

## Fireplace

# Fan Not Checked Looked ok. It is getting worn. Damper **Operational:** Yes None Sticks Unsecured Corrosion Creosote Top mounted damper. Worked ok. Old damper removed. **Chimney Flue**

✓ Not Checked Soot

Advise Sweeping and Inspection

Contact a qualified chimney sweep to ensure the flue is cleaned properly with no blockages and to test and inspect the damper to ensure safe operation prior to use.



THE HOME OF HOME INSPECTION<sup>™</sup> Date: 22-Jul-2011

7 Glenview Pl.,, Huntington, New York 11743

2 Bathroom	าร				Bathrooms
Location					
Basement	✓ 1st Floor	✓ 2nd Floor	3rd Floor		
Water Flow					
✓ Normal	Suspect	Low	Water off		
Floor				Damaged:	No
Worn	Crack	Ceramic			
Wall				Damaged:	No
Patched	Crack	✓ Drywall	Ceramic	Ũ	
Ceiling				Damaged:	No
Patched	Crack	✓ Drywall	Tile		
Window				Operational:	Yes
✓ Vinyl ☐ Mildew	✓ Double Hung Stain	Casement	✓ Thermal		maged
Old skylig	ght in 2nd floor bath	had a crack in it. I	Budget to replace.		
Receptacle					
Install GFCI	Open Ground				
2nd floor	GFCI was in the ele	ctric panel.			
Door					
Binds	Damaged	Hinged	✔ Wood		
Exhaust Fan				Opera	tional
Recommend I	Installation				
	ctrician remove exha o into unit.	ust fan unit from	tub area. This is a	possible shock or fire haza	rd. Water could
Sink				Damaged:	No
Worn	Chip				
Faucet				Operational:	Yes
Leaks	No Shut-off	Sticks	Unsecured		
Trap/Drain				Damaged:	No
Unsecured	Improper Trap	Slow Drain	Corrosion	Leak	
Vanity				Damaged:	No
Worn	✓ Laminate	Wood	Mildew	Missing Hardware	

THE HOME OF HOME INS	PECTION <sup>SM</sup> Date: 22-Jul	-2011	///////////////////////////////////////	7 Glenview Pl.,, Hunt	ington, New York 11
2 Bathrooms	6				Bathrooi
Counter					
Unsecured	Solid Surface	Granite	Regrout	Mildew	Scratch
Toilet				Operation	al: Yes
No Shut-Off	Tank Loose	Unsecured	Crack	Leak	
Tub and Show	ver Enclosures			Damag	ed: No
Unsecured	Ceramic	Cultured Marble	Regrout	Mildew	Crack
Seal tile w	ith good tile sealer to	o help keep water	out.		
letted Tub				Operation	nal: No
Not Tested Jetted tub	GFCI Protected did not work. Have motor was in bedroo	checked.	Corrosion	Operation	nal: No
Jetted tub Access to	did not work. Have motor was in bedroo	checked.		Operation	nal: No
Not Tested Jetted tub Access to Access to whirt	did not work. Have motor was in bedroo	checked. om through the wa		Operation	

Professional Home Inspection PILIAP TO POSt		<b>Bob Van Stry</b> 16000005960
THE HOME OF HOME INSPECTIONS	Date: 22-Jul-2011	7 Glenview Pl.,, Huntington, New York 11743

Floor Worn	Crack	Carpet	<b>∨</b> Vinyl	Wood	Ceramic
Wall					
Patched	Crack	✓ Drywall	Brick	Wallpaper	Ceramic
Ceiling					
Patched	Crack	▼ Drywall	Stipple	Wood	Tile
Lighting				Operation	al: Yes
None					
Receptacles					
Install GFCI	No Ground				
Worked ok.	GFCI was in the e	lectric panel.			
Window				Operation	al: Yes
Binds	Not Tested	✓ Double Hung	Casement	Bay	✓ Thermal
Aluminum	✓ Vinyl	Wood	Damaged	Mildew	Stain
Old skylight	t. Budget to replace	э.			
Sink					
Worn	Chip	✓ Single	Double	Stainless	Enamel
Faucet				Operation	al: Yes
No Shut-Off Val	lve	Sticks	Unsecured	Corrosion	Leak

**Kitchen** 

Professional Home Inspection	-			1		<b>Bob Van Stry</b> 16000005960
THE HOME OF HOME INSPECTIC	Date: 22-Jul	-2011	1///	7 Glenview Pl.,	, Huntington, Ne	ew York 11743
						Kitchen
Trap/Drain	]Improper Trap	Slow Drain	Corrosion	Da	amaged:	No
Sink waste pip Have a plumbe		d correctly. Vent u	nder sink could g	o bad and ver	t waste gases	into room.
Counter	7				amaged:	No
Unsecured	Laminate	Granite	Regrout	Mildew	Worr	1
Cabinet	11	Weed	Mildew		amaged:	No
☐ Worn ✓ Cabinets looke	]Laminate ed ok.	Wood		Missing H	lardware	
Range Hood and	Exhaust Vent			Oper	ational:	Yes
☐ Cooktop Exhaust ✓ Ductless Exhaust		☐No Exhaust ☐Filter Clogged	□ No Light	Noisy		
I recommend v	enting to the ex	terior.				
Major Appliances Tested ON/OFF onl Dishwasher		✓ Did Not Test All ☐ Wall Oven	Functions	Refrigeration Refrigeration	tor 🔽 Stove	2
Heat Source	]Thermostat	Convector	Air Register			

Professional Home In	uspection			1		<b>Bob Van Stry</b> 16000005960
THE HOME OF HOME INS	7 Glenview Pl.,, Huntington, New York 11743					
Living Room	n, Dining Room	, Hallway, Bedro	oms		In	terior Rooms
Interior Gener	al Comments					
make up a identify the at the time The comm improveme	nd materials and e individual room i of the inspection	I to give an overview	e listed in this sec oom, Living Rooi	ction. Specific co m ) and noted con	nditions an ditions sho	d remarks will ould such exist
Floor				i		_
Worn Wood floo	Crack	Carpet et on floor looked ok	Vinyl	✔ Wood	[]Cei	ramic
Hallway Stairs				Dam	naged:	No
✓ Wood	Carpet	✓ Wood Handrail		Bui	Damaged. No	
Wall						
Uneven	Crack	✓ Drywall	Wallpaper	✓ Wood Composite		
Attic acces	ss was thru door i	n the 2nd floor hallw	ay			
Lighting				Operat	ional:	Yes
Worked of	с.					
Receptacles			Damaged: No			
Open Ground	No Ground	Have Electricia	n Update			
Ceiling						
Patched	Crack	✓ Drywall	Stipple	Wood	□ Tile	2
Window				Operat	ional:	Yes
Binds Aluminum	☐ Not Tested ✓ Vinyl	✓ Double Hung ↓ Wood	Casement	✓ Bay ☐ Mildew	✓ The Sta	
Tested wir	ndows opened ok					
Door				Operational: Yes		
Binds	Damaged	✓ Hinged	Wood			
Doors look	ked ok.					
Patio/Door				Operat	ional:	Yes
Binds	Damaged	Sliding	✓ Hinged	Wood	✓ Me	tal
	r looked ok. oors are ok.					

Professional Home	Inspection				<b>Bob Van Stry</b> 16000005960
THE HOME OF HOME IN	11/10	Jul-2011	///////////////////////////////////////	7 Glenview Pl.,, Huntington	, New York 11743
Living Roor	n, Dining Roon	n, Hallway, Bedr	ooms	Ir	nterior Rooms
Closet/Door				Operational:	Yes
Binds	Damaged	Light	✓ Hinged		
	ors need adjustme ess in 2nd floor be	ent to operate bette droom closet	r.		
Heat Source					
None	Thermostat	Convector			



7 Glenview Pl.,, Huntington, New York 11743

## Additional Comments

## **General Comments**

Main areas of concern were: Fix bulge in roof if needed. Budget to replace old skylights. Extend leaders away from home. Panel has too many breakers. Whirlpool tub not working. Vent kitchen sink better. Old galvanized waste pipes could be a problem in the future.

#### SERVICE RECORDS AND DOCUMENTATION

It is recommended to obtain service, update and replacement records from the current owner prior to the close of escrow for any work performed in the home to help determine associated upkeep costs, age of related components and possible existence of warranty or guarantee from a manufacturer or service company.

#### **REPAIRS AND RENOVATIONS**

All updating, maintenance and repairs performed in the home whether recommended in the report or otherwise should be performed only by qualified and licensed individuals. This provides some assurances as to the quality of work and accountability for any work contracted. It is recommended to obtain multiple estimates and check references for all contractors hired to conduct work in a home.

#### CONSTRUCTION REGULATIONS / CODE COMPLIANCE

A standard home inspection does not include evaluation of a property for compliance with building or health codes, zoning regulations or other local codes or ordinances. Such inspections, if required, are normally performed by local officials or private code inspection agencies at the time of the original construction or renovations. Codes are revised on a periodic basis; consequently, existing structures generally do not meet current code standards, nor is such compliance usually required. Any questions regarding code compliance should be addressed to the appropriate local officials.

#### LEAD BASED PAINT:

It has been determined that this home was built before 1978 and therefore stands a high risk of having lead based paint present. Not only is lead not good for your health, under the EPA ruling 40 CFR Part 745 effective April 22, 2010, any renovation, remodeling or painting not performed by yourself must be done by a certified contractor following lead-safe practices and this could lead to higher prices than similar contracts performed on homes that do not have lead based paint present. It is recommended that a preliminary screening for lead based paint be conducted to determine the likelihood of the presence of lead before closing if this is a concern for you.

#### FINAL WALK-THRU INSPECTION

A final walk-thru inspection of the property by the purchaser is customary in real estate transactions and is normally conducted a day before closing of the transaction. At this time, all personal property and furnishings should have been removed and an unobstructed examination of the interior is possible. You are advised to walk through and carefully observe the condition of the property for any flaws or defects that may not have been visible during the home inspection or which may have occurred since then. You are especially urged to look for any signs of water leakage and physical damage. Since the condition of mechanical equipment can change over any given time period, it is your

responsibility to verify the functional condition of the various components and systems prior to settlement.

7 Glenview Pl.,, Huntington, New York 11743

## Additional Comments

You are advised to operate all appliances, plumbing fixtures and faucets, heating and cooling systems (weather permitting) and all other equipment included in the sale of the property.

## Limitations

Chimney - The interior of chimneys and their flue liners are not visible on our visual inspection. You are advised to obtain the services of a qualified chimney sweeper or other qualified personnel to perform a complete inspection and tune up of your heating appliances and fireplace prior to use.

Occupied Home – The home is occupied by the current owner with their personal belongings and furniture which limits some areas of inspection.

Circuit Sizing - The Inspector is required to address the compatibility of conductors and overcurrent devices. In some instances, general trade procedures include over-sizing overcurrent devices to guard against nuisance (e.g. air conditioning units, dryers). The Inspector is not required to evaluate such general trade procedures, but to inform you of incompatibility.

Skylight – Skylights are an excellent source of light to dwellings, but frequently have condensation problems and are always a risk for potential future water leaks because flashings require regular ongoing maintenance by an experienced roofer.

Finished Basements - The finishing of the basement prevents visual inspection of foundation walls, floors, mechanical and structural components. Normal/High moisture readings were found at time of inspection. Despite these tests results, a dry basement at this time or at any time in the future is not guaranteed.

## **Supplementary Comments**

Recommend installing & testing regularly Carbon Monoxide Detectors (locate in bedroom area + rooms with fireplace) and new Smoke sensors (mandatory every floor). Propane & Natural Gas sensors are also available in stores. (\$35-\$60)

It is important that water from eve troughs drains well away from house - at least 6 feet away from wall. Also it is usually better to reposition downspouts to drain water above ground and away from house, then cap drains.

Some ceilings and walls may require nail holes, nail pops, dimples and/or cracks to be patched before painting.

Monitor the roof and attic on a seasonal basis for leaks and (wind) damage. Repair as soon as possible. It is very important that water & runoff drain away from foundations to minimize chance of water leakage into the basement, as cracks in foundation walls are common. Make sure the ground, patios and walkways slope away from the house for the first six feet.

Not all windows or doors may have been checked due to obstructions (i.e. blinds, curtains and/or furniture). Not all receptacles/outlets tested due to limited accessibility (i.e. furniture, clutter and/or obstructions). Ceramic floor tiles, especially larger ones, can crack unexpectedly or become loose - repair as required. Have a cesspool company inspect cesspool. You may need to have the cover dug up to see the cesspool. Skylights frequently have condensation problems and/or can leak - monitor regularly.

If thru wall a/c units are installed incorrectly, its possible for the condensation water to leak between the walls and rot out the structure. Damage will be hidden and beyond the scope of this inspection.

## **Report Commentary**



THE HOME OF HOME INSPECTION<sup>™</sup> Date: 22-Jul-2011

7 Glenview Pl.,, Huntington, New York 11743

This summary is not the entire report. The complete report may include additional information of concern to the client. It is recommended that the client read the entire report.

## **1.0** Property and Exterior

## 1.1 Landscaping

Trim and maintain vegetation away from structure to reduce moisture damages and premature wear of finishing materials.

## 1.2 Deck/Patio

May need to add more support to the roof above to handle heavy snow loads.

## 2.0 Garage

## 2.1 Type

Cluttered garage. Hard to see everything.

## 2.2 Access Door

Add self closing hinges for added fire safety. Add handrail to steps for added safety.

## 3.0 Roof Structure

#### 3.1 Main Roof

Buckling seen in the back lower roof. Could be caused by extreme heat and sheathing being installed to tightly. If bulge does not go down when roof cools, you will need to cut out bulge and patch roof. Have a roofer check further.

Add some roof vents to the lower roof.

## 3.2 Accessory

Both skylights are old. The home made old skylight has a lot of caulk on it and could be a problem in the future.

The skylight above the bathroom has a crack in it and is old. Budget to replace both skylights.

## 3.3 Flashing

Secure stack vent flashing better.

## **4.0** <u>Attic</u>

#### 4.1 Ventilation

I recommend adding ridge vents to get better airflow in attic spaces.

## **Report Commentary**



THE HOME OF HOME INSPECTION™ Date: 22-Jul-2011

7 Glenview Pl.,, Huntington, New York 11743

This summary is not the entire report. The complete report may include additional information of concern to the client. It is recommended that the client read the entire report.

## 5.0 <u>Basement/Structure</u>

## 5.1 Floor

Basement looked ok. French drains system was seen around the perimeter of the basement.

## 5.2 Railing

Need to add a gripable handrail at the top of the stair case. Current handrail is unsafe.

## 5.3 Floor Joist

Some minor water damage to subfloor seen under bathrooms.

## 6.0 <u>Electrical Service</u>

## 6.1 Distribution Panel

Panel looked ok.

## 6.2 Fuse

To many breakers seen in the panel for 100 amp service. Have an electrician check further. Otherwise panel looked ok.

## 6.3 Receptacles and Lighting

Remove exhaust fans out of the tub area. Possible shock hazard.

## 8.0 <u>Plumbing Components</u>

## 8.1 Hot Water Tank

Hot water tank looked OK.6 years old.

## 9.0 <u>Bathrooms</u>

2 Bathrooms

## 9.1 Window

Old skylight in 2nd floor bath had a crack in it. Budget to replace.

## 9.2 Exhaust Fan

Have electrician remove exhaust fan unit from tub area. This is a possible shock or fire hazard. Water could splash up into unit.

## 9.3 Jetted Tub

Jetted tub did not work. Have checked.

## **Report Commentary**



THE HOME OF HOME INSPECTION<sup>™</sup> Date: 22-Jul-2011

7 Glenview Pl.,, Huntington, New York 11743

This summary is not the entire report. The complete report may include additional information of concern to the client. It is recommended that the client read the entire report.

## **10.0** <u>Kitchen</u>

## 10.1 Receptacles

Worked ok.GFCI was in the electric panel.

## 10.2 Window

Old skylight. Budget to replace.

11.0 Interior Rooms

Living Room, Dining Room, Hallway, Bedrooms

## 11.1 Lighting

Worked ok.

## 11.2 Door

Doors looked ok.

## 12.0 Additional Comments

## **12.1 General Comments**

Main areas of concern were: Fix bulge in roof if needed. Budget to replace old skylights. Extend leaders away from home. Panel has too many breakers. Whirlpool tub not working. Vent kitchen sink better. Old galvanized waste pipes could be a problem in the future.

# **Galvanized Steel Water Pipes**

## What is Galvanized Steel Pipe?

Galvanized refers to a zinc coating added to steel pipes to protect them from rust. Galvanized steel was used for residential supply plumbing until around 1950. Although it was considered an effective resistant to corrosion at the time, it proved to have a limited service life of approximately 50 years. Over time, water passing through the pipes literally consumes the zinc. Once the zinc is gone, the exposed steel will then start to rust.

## **The Problems**

Galvanized steel pipe has not been used in residential homes since around 1950. Any galvanized steel found in homes today, therefore, will generally be well past its shelf date. If you have galvanized steel pipes, consider replacing them, especially since rust is not the only problem you will face. Other problems include:

Poor water flow

- galvanized steel pipe rusts from the inside out, diminishing the effective cross-sectional area. Any pipe found today will likely have an interior comprised mostly of rust.

- Rust Leak
- Rust in the water you may see rust in the water when you first turn on the taps. It will, however, quickly clear as you run the water, but unsightly stains may develop on plumbing fixtures.
- Leaks the pipe eventually rusts right through, usually at the threaded joints where the steel is the thinnest, causing leaks.
- **Home insurance** many insurance companies will not insure homes with galvanized steel pipe because of the risk of major leaks.






Page 42 of 59

## **Recognizing Galvanized Steel Pipe**

- A silvery grey color indicates weathered galvanized steel pipe
- The pipe connections are often threaded
- A magnet will stick to galvanized steel pipe but not to copper, lead, or plastic
- The flow from the hot tap is distinctly different than the flow from the cold
- Rust stains can be found near the drain in a sink

Recognizing galvanized steel is easy, but *finding* it can be a challenge. If the plumbing in your home has been upgraded at some point, galvanized steel pipe may be located in areas difficult and/or disruptive to access. For instance, a past upgrade might have involved replacing the horizontal runs of pipe, which tend to corrode faster than the vertical runs (risers), leaving the latter, therefore, in place. Risers inside walls are often difficult or impossible to see. Furthermore, hot water pipes often get replaced while cold are left behind since the hot corrode faster than the cold. Galvanized steel pipes, therefore, tend to go undetected until a leak appears, or until the walls are opened during a renovation.


Although galvanized steel does not present a health hazard, you should still consider replacing it since you run the risk of major leaks that may cause serious damage to your house, resulting in expensive repairs. Replacement will also clear up minor problems, such as poor water flow. If you find galvanized steel in your home, contact a plumber to have it replaced. Do not wait for a leak!



Pillar To Post®, the home of home inspectionWe welcome your comments and suggestions for future Information Series topicsinfo@pillartopost.com1-800-294-5591www.pillartopost.com

# Lead Based Paint

Older paint contains lead. Over the years, governments have regulated the phasing out of lead in paint entirely. If your house was built before 1960, the paint used during construction would have contained a great deal of lead. Reduction started soon after this and lead paint was completely eliminated by the 1980s. If your house was built before 1978, the paint still likely has some lead in it and the EPA has ruled that after April 2010 all these homes will require special procedures when renovations are performed.



So what's wrong with lead based paint? Lead is unhealthy if ingested and it is surprisingly easy to ingest. It has a way of finding its way into our diets, particularly into the diets of toddlers. For instance, painted door jambs and window sashes create paint dust during use. For toddlers who spend a great deal of time on their hands and knees, and who 'test' the world through their mouths, this dust presents a serious health hazard if it contains lead. The most troubling issue with lead however, is that it can also be absorbed through the skin upon contact.

# Testing

Knowing if you have lead based paint is half the battle. The paint can be tested on site by a home inspector using EPA approved equipment that can give you instant results. The alternative is to send a sample to a lab for testing. Your home inspector can collect the samples and submit them to an approved laboratory for analysis.

# Dealing with Lead Based Paint

Living with lead should not be an option, especially if there are children under the age of six in a home. Constant cleaning and encapsulation may be good temporary measures, but you will be better served to remove the offending coatings, surfaces or components. The only way to be certain about the presence or absence of lead, is by testing, whether by virtually instant onsite methods or samples submitted to an approved laboratory.





©2010 Pillar To Post Inc.

## **Replace:**


Wear surfaces can be replaced rather than encapsulated. For example, you can remove and replace door jambs with new wood.

## Remove:

Where encapsulation or wood replacement is not practical, you can remove the paint using chemical strippers. This task is time consuming and expensive and should only be done by an expert lead abatement contractor since proper containment is essential.

## A Few Tips

- Lead poisoning does not happen overnight so do not panic
- For peace of mind, you can test your children for lead poisoning with a simple blood test done by your family physician
- Have your home tested for the presence of lead paint by a qualified home inspector using EPA approved equipment
- Do not attempt to remove lead based paint yourself as you may create a much bigger problem by spreading lead dust around your house




## Pillar To Post<sup>®</sup>, the home of home inspection

We welcome your comments and suggestions for future Information Series topicsinfo@pillartopost.com1-800-294-5591www.pillartopost.com

# **Attic Thermal Insulation**

The attic accounts for a large percentage of a house's heat loss and heat gain. Attic insulation reduces heat loss in the cold months. and prevents heat build up in hotter months, making it a priority for insulation. In new construction. insulation levels for the attic are higher than all other areas. In an old home, the attic is the first place for insulation upgrades. The attic is comparatively easy to insulate since it usually presents no space constraint, making it easy to add a lot of insulation.



# **Ventilation**

Critical to a healthy attic is good ventilation, with airflow circulating into and out of the attic. Circulation helps stabilize the attic temperature and remove moisture. Ideal ventilation has vent openings low on the roof and vents high on the roof to create draft. Air will flow naturally in the low openings and out the high openings. This is usually accomplished with soffit vents at the eaves and roof top vents (mushroom vents) on top of the roof. There are many other possibilities as well.

Many homes in which the insulation has been upgraded does not have appropriate ventilation either because the insulation contractor did not add vents when insulating or because insulation now covers the soffit vents, restricting the air flow. To solve this problem, baffles can be added to create an air channel past the insulation at the soffit. Air can then flow freely into the attic and then out the vents on the roof top. If additional roof top vents are needed, it is a very easy and inexpensive upgrade.

# Air Leakage

The thought behind current building science recognizes that while attic ventilation is important, equally important is sealing air leaks from the rest of the house to the attic, especially in cold climates. In a typical home, recessed light fixtures, bathroom vents, plumbing stacks, chimneys and wall cavities present numerous potential air leakage paths to the attic. Air leakage from the house causes many problems including condensation,





©2007 Pillar To Post Inc.

rot, mildew and in cold climates – ice dams.


Ducting that runs through the attic should be well sealed and properly insulated. There is no point heating and cooling your attic.

## **Do Not Disturb the Insulation**

It's best not to disturb the insulation in the attic. Some attics have vermiculite insulation. Most vermiculite insulation contains small amounts of asbestos. Disturbing the insulation can cause a cloud of asbestos, a substance it is best to avoid or to which exposure should be limited. In some cases, the vermiculite lies under a layer of a different type of insulation. Visually, it may look like you have ten inches of fiberglass when, in fact, you may actually have four inches of vermiculite and six inches of fiberglass. If you have to disturb the insulation, check what kind of insulation you have first and take appropriate precautions. A standard dust mask is not good enough for asbestos.

## **Upgrading Attic Insulation**

If you are upgrading your attic insulation, make sure you hire a contractor who is knowledgeable about the techniques and codes for your area. Good contractors will asses the insulation type and condition, as well as air leakage from the house and ventilation.




# Hot Water Heat

A heating system that heats the home by circulating hot water is called a hydronic heating system. The device that does the heating is called a boiler even though it does not actually boil the water. Water picks up heat as it flows through the boiler. Heat is released at the radiators in each room. Cool water flows back to the boiler. A circulating pump keeps things moving. The same water circulates through the system over and over again.

# **Radiators and Convectors**

Usually a home will have either radiators or baseboard convectors, not both. The traditional radiator is made of cast iron and stands on the floor against a wall. If you have ever lived in an old home in a cold climate, the radiators are what you put your socks, hat and mitts on to dry them out and keep them warm and ready. Since radiators are massive, they heat up slowly and ooze



heat into the room over a long period of time. This makes for very even heating, a benefit of hot water heat.

Hot water baseboard convectors look like electric baseboard heaters. They don't take up as much space as radiators. Modern radiators and convectors come in all shapes and sizes including decorative wall panels and even heated towel racks for the bathroom.

# Radiant Heating

In-floor hot water radiant heat is an alternative to radiators and convectors. Pipes are embedded in the floor and heat energy is radiated into the room. This kind of heat is getting more popular in North America.

# **Benefits of Hot Water Heating**

There are many benefits to hot water heating. Here are a few: **Silent:** A properly installed hydronic heating system should be nearly silent throughout the home.

**Even heat:** Since the system heats up slowly and cools slowly, the heating is very even.





©2007 Pillar To Post Inc.

Page 48 of 59

Doesn't circulate dust: Hydronic heating systems do not stir up dust and blow it around the house. This is healthier and there's no filter to change.

Doesn't circulate odors: Hot water does not circulate odors like forced air heating does. Easy to create separate zones: Piping is easier to control than air ducting. It is easy to create separate heating zones in the house with separate thermostats.

## What's the Downside?

**Cooling:** One reason hot water heating is not more popular in North America is that air conditioning cannot piggyback on it. The air ducting and blower of a forced air heating system can be used for cooling by adding the cooling components into the forced air heating system. If you have hot water heating, you will have to add independent ducting throughout the home to provide cooling.

**More expensive:** There are fewer options when it comes to hot water heating. Boilers tend to be more expensive than forced air furnaces. Repairs, modifications and extensions to the system are more expensive too.


## **Maintenance Tips**

- Leaks should be dealt with promptly.
- Look for two common leakage points:
  - Radiator control valves on old cast iron radiators look where the pipes go into the base of the radiator

**Pressure relief valve on the boiler** – this could indicate a 'water-logged' expansion tank or simply a defective valve.

- Air gets trapped in the radiators, reducing the amount of heat given off. Most radiators have a bleed valve at the top. Open the valve and let the air hiss out. When you see some water come out, close the valve.
- Yearly service on any heating system is a good idea.

Hot water heating accounts for a small percentage of the residential heating systems in North America while the experience is exactly the opposite in Europe. With modern features and people seeking healthier alternatives, hot water heating is now becoming more popular in North America.




Hot Water Baseboard Convector

Pillar To Post®, the home of home inspectionWe welcome your comments and suggestions for future Information Series topicsinfo@pillartopost.com1-800-294-5591www.pillartopost.com1-800-294-5591

# Fireplaces & Wood Stoves

There is nothing like the ambiance of a wood burning fireplace. But like any heating system, wood burning fireplaces require maintenance to ensure safe and efficient operation. They should be inspected and cleaned every year. This process is not a do-it-yourself job.

Most chimney flues are not readily visible when you look up the chimney. Often, you cannot properly inspect the flue until it has been cleaned. It is important to get your chimney and flue cleaned and inspected every year for a number of reasons, but the two main reasons involve safety. Simply put, get the flue cleaned to avoid a chimney fire. A chimney fire occurs



when the combustible deposits in the chimney (creosote) ignite. A chimney fire involves flames shooting out the chimney top, and air roaring up the chimney to feed the fire. It is as loud as it is dangerous! A chimney sweep can remove the creosote deposits that potentially cause fires. Second, have the flue inspected. A flue liner in good condition will help protect your home if you do have a chimney fire. An inspection of the chimney flue is not part of a home inspection. Call a trained technician to clean and inspect your chimney flue.

# Old Unlined Chimneys

Fireplaces in old homes may not have clay flue liners. It is particularly important to seek the advice of an expert for these old chimneys. Unlined brick chimneys come in two varieties: single thickness (four inches of brick), and double thickness (eight inches of brick). There is little debate that a four inch thick, unlined chimney is not acceptable. This chimney should either have a liner added, or the fireplace decommissioned. For chimneys with eight inch brick, conflicting opinions abound. Some believe these are safe as long as the brick and mortar are in good condition, and the flue is cleaned regularly. Others believe





©2007 Pillar To Post Inc.

that double brick flues should also have a liner added. Consider hiring an expert who does not offer a chimney lining service. This will give you an unbiased expert opinion on whether a liner is needed.

## **Glass Doors**

Some fireplaces have glass doors across their opening. The glass doors reduce heat loss when the fireplace is not running. Most glass door systems added to an existing fireplace are not designed to be closed when the fire is lit. On the other hand, some high efficiency zero-clearance fireplaces are designed for operation with the doors closed. If you are not sure, ask the technician who cleans and inspects your fireplace and flue.

## Wood Stove

A wood stove is more efficient than a fireplace. Modern wood stoves burn wood cleanly and efficiently. Like fireplaces, the wood stove must be cleaned and inspected annually. An expert will check the flue, the hearth and the clearance to combustibles. The clearance to combustibles information is listed on the data tag on the wood stove.

## Zero-Clearance

Today, a fireplace can be added to almost any home. A zero-clearance fireplace can be installed directly against an existing wall and supported by the existing floor (a foundation is not required). A good installer is a must for this job.

# **Tips for All Wood Burning Fireplaces**

- Do not burn trash.
- Do not burn pressure-treated To Chimney or painted wood. Burn seasoned hardwood. Softwood will cause creosote to build up more quickly. Load the logs near the back of the fireplace. Use the spark screen. Make sure smoke and CO detectors are functioning. Door Have the chimney and fireplace or wood stove inspected and cleaned Handle annually. Air Intake Hearth


Pillar To Post®, the home of home inspectionWe welcome your comments and suggestions for future Information Series topicsinfo@pillartopost.com1-800-294-5591www.pillartopost.com

# Ice Damming

Ice dams are large build-ups of ice found at the bottom edge of the roof. A small amount of ice may not cause an immediate problem, but if the ice continues to build up, it will block the water flow down the roof, causing water to back up under the shingles and leak into the soffit area, or into your house.

# Here's How it Happens

- Ice dams form when there is a blanket of snow on the roof.
- Heat from the attic melts snow above.
- Water then runs down the roof between the shingles and the blanket of snow.



- When the water reaches the roof overhang (bottom edge of the roof), it encounters an area of the roof that is not getting any heat from the attic so the water freezes.
- As this condition progresses, the ice at the bottom edge of the roof becomes thicker until it blocks water flow.
- Water backs up and starts to leak into the soffit area and eventually into the home.

The root cause of ice damming is heat from the attic. When you control the heat, you control the ice dam. Here are three ways you can control the heat in the attic:

- Air seal the attic from the house: recent research indicates that air sealing is paramount. Air leakage from the house heats up the attic. Not only will this attic heat contribute to ice damming but air leakage will cause condensation on roof decking and framing, leading to rot. Bathroom vents, recessed light fixtures and plumbing stacks are all potential air leakage spots.
- **Insulate the attic:** if the attic insulation is insufficient, upgrade it to reduce the conductive heat transfer into the attic.
- **Ventilate the attic:** proper ventilation and air flow through the attic will help control the attic temperature. Make sure insulation is not blocking vents. Also make sure vents are evenly distributed, with some high on the roof, such as roof-top vents and some lower,





©2007 Pillar To Post Inc.

Page 52 of 59


such as soffit vents. Do not try to improve attic ventilation by adding more roof top vents without adding corresponding lower vents such as soffit vents. Unbalanced venting can actually create negative pressure in the attic, drawing more air leakage from the house into the attic.

## **Un-Insulated Attics**

You would think that un-insulated attics would generate the worst ice dams. In fact, un-insulated attics tend not to create an ice damming problem because so much heat is lost through the attic that the snow melts as it lands on the roof. A snow blanket has no opportunity to form. Any insulation upgrades to an un-insulated attic must be accompanied by air sealing and ventilating the attic.

## **Heating Cables**

In some cases, the roof configuration may not be conducive to preventing ice dams, leaving only one option: heating cables, often called heat trace. The heating cables prevent ice from building up in the first place, or, at the very least, the cables will melt channels in the ice to allow water to flow off the edge of the roof. The heating cables use a significant amount of electricity and should be considered only if there is no other solution.




Pillar To Post®, the home of home inspectionWe welcome your comments and suggestions for future Information Series topicsinfo@pillartopost.com1-800-294-5591www.pillartopost.com

# Smoke Alarms



incredible success story. Once the concept took hold in the 1970s, it wasn't long before the fire death rate was cut in half! Now, more than three decades later, most homes have at least one smoke alarm but we still have a problem - the smoke alarms aren't working! In one quarter of the homes with smoke alarms. the smoke alarms don't work. The cause is missing, dead or disconnected batteries (National Fire Protection Association), Pillar To Post® would like to encourage you to pay more attention to your smoke alarms.

Smoke alarms are an



The two key goals of smoke alarms are –

- To wake you up. You can't sense smoke and flame when you are asleep.
- Early warning. The sooner you know about a fire the better the possible outcome

# **Placement of Smoke Alarms**

While you should consult the instructions provided with the smoke alarm, here are some general guidelines. We do not address local bylaws and codes here.

- There should be at least one smoke alarm per floor including the basement.
- Smoke alarms should be placed outside every separate sleeping area. Many authorities suggest an alarm inside each bedroom as well.
- The alarm can be placed on the ceiling or high up on the wall. If the alarm is on the ceiling, it should be at least four inches away from any walls. If the alarm is on the wall, it should be at least four inches but not more than twelve inches from the ceiling.
- Peaked ceilings have stagnant air at the top. The smoke alarm should be three feet from the highest point.
- Do not place the smoke alarm where it could be affected by drafts such as next to a window or air vent.





©2007 Pillar To Post Inc.

Page 54 of 59

# Maintaining

Test the smoke alarm once per month by pressing the test button until the alarm sounds then release the button. If the smoke alarm is battery operated, replace the battery every year. If you hear a chirping sound from the smoke alarm, change the batteries. Dust or vacuum the surface periodically. Replace the entire unit if it is older than 10 years or if you are not sure how old it is. Print the installation date inside the cover.

## **False Alarms**


Nuisance tripping of your smoke alarm is bound to happen occasionally. Unfortunately, many people remove the battery to silence the alarm with the good intention of replacing it after the smoke clears. Here are some better ways to deal with nuisance tripping: Use an alarm with a 'hush button'. Move the smoke alarm a little further from the kitchen area. Try a different type of alarm. Some experts say that a photoelectric smoke alarm is a little less sensitive to common causes of false alarms.

## Hard Wired Alarms

Many homes today have smoke alarms wired right into the household electrical system. In addition, some homes have interconnected smoke alarms. This means if one alarm in the home sounds then the others sound as well.

## **Escape Plan**

Smoke and flame can spread quickly so you need to react quickly. It is vital that you and your family know what to do on hearing a smoke alarm. You should plan an escape route from every area of the home and identify a safe area to meet outside the home. You should rehearse the escape plan with your family. Walk through and identify obstacles that may slow you down such as windows that are jammed or exits that are crowded with storage etc.



Pillar To Post®, the home of home inspectionWe welcome your comments and suggestions for future Information Series topicsinfo@pillartopost.com1-800-294-5591www.pillartopost.com

# Carbon Monoxide

Carbon monoxide, or CO, a byproduct of incomplete combustion of fossil fuels, is a colorless, odorless gas. Breathing CO reduces the blood's ability to carry oxygen. In severe cases, CO can cause death.

**Defective or malfunctioning** fossil fuel appliances, or inappropriate use of appliances that burn fossil fuel close to or inside the home can pose a serious health hazard. Here are a few examples of dangerous operations:

- Running an automobile or gas lawn mower inside the garage
- Operating a barbeque inside the home
- A gas or oil burning furnace with a blockage in the chimney
- Kerosene space heaters
- Operating a generator in the home during a power failure

# Symptoms of Carbon Monoxide Poisoning


Symptoms of carbon monoxide poisoning include headache, dizziness, nausea, vomiting, weakness, chest pain, confusion, and loss of consciousness. Carbon monoxide poisoning can lead to death. Low level poisoning may go unnoticed because it may be mistaken for the flu.

# Carbon Monoxide Detector


You should have at least one carbon monoxide detector in your home. In some geographic areas, a CO detector is required by law. The CO detector should be placed where you can hear it if it goes off when you are asleep. A CO detector does not have to be placed on the ceiling, since unlike smoke, CO has approximately the same weight as air so it mixes












uniformly throughout the room rather than floating up to the ceiling. To avoid false alarms, do not install the detector next to heating and cooking appliances, vents, flues, or chimneys. Make sure you read and follow the operating, placement, and testing instructions that come with the detector.

If the carbon monoxide detector alarms, take it seriously.

## **Avoiding CO Poisoning**

- Have your heating systems serviced every year by a qualified technician.
- Have your fireplace chimney cleaned and inspected every year.
- Install at least one CO detector in your home and replace the batteries twice per year.
- Open the garage door prior to starting your car; drive the car out promptly. Do not leave it idling in the garage. Do not use a remote car starter when the car is in the garage.
- Do not use a charcoal or propane barbeque in the home.



Pillar To Post®, the home of home inspection

We welcome your comments and suggestions for future Information Series topicsinfo@pillartopost.com1-800-294-5591www.pillartopost.com

# SKYLIGHTS

People are drawn to areas with natural light. What's more, there is something special about natural light from above, bringing the sky indoors. Skylights can make a dark room bright, provide ventilation and add architectural appeal.

# As Lighting

A skylight can be a problem solver, bringing natural light where it would be difficult or impossible to add a window. Here are some examples -



- Inside wall area of a duplex (semi-detached) or a home on a zero lot line.
- Natural illumination of a stairway.
- Natural lighting where privacy is required such as a bathroom.
- Small lots where windows would be looking directly onto a neighbors home.
- Where an attic has been renovated into a living area. Some skylights are manufactured to satisfy attic egress requirements of building codes as well.



# As Ventilation

Skylights can be of fixed design or openable. The openable type can provide natural ventilation. There are also fixed skylights that have a venting option. In these, there is a vent flap that can be opened. Openable skylights are either manual or automatic.

# Light Shaft

Skylights on cathedral ceilings bring light directly through the roof plane into the living area. Skylights on homes with an attic are a little more complicated. You have to punch a hole through a large attic area. The hole through the attic area is called the light shaft.

The simplest light shaft is a channel that extends straight down from the skylight above. This is the easiest to frame and interferes the least with existing framing. It's also the least interesting architecturally and brings in the least amount of light. A more interesting design is to flare the light shaft out to bring in more light. The flare can be a simple one sided flare or a more complicated two sided or even four sided flare. The more sides you flare, the more complicated and disruptive the framing.

# Heat

One of the most important things to consider for warm climates is that skylights will add considerably to the heat gain and thus the air conditioning load. In hot climates, care should be given to the orientation of the skylight. For example, south or west facing skylights have a much greater heat gain than north or east facing skylights. In addition to





©2008 Pillar To Post Inc.

Page 58 of 59

orientation, choosing the correct skylight for your climate helps. A skylight that is ideal in one climate may be completely wrong in another. There are many options available such as low-e glass and tinted or reflective glass. Your installer should be familiar with the different options and the ratings on the skylight. There are several different parameters that are rated on skylights. For warm climates the SHGC or Solar Heat Gain Coefficient is one of the most important. SHGC represents how much heat from the sun penetrates the skylight. A low tech solution to heat gain is a shade for the skylight.

Different orientations have different light characteristics as well. North facing skylights have steady light levels throughout the day and the light is very soft. East and west facing skylights have varying light levels throughout the day. South facing skylights gives the most light but the light is also very hot and harsh.

## Installation

When a roof leaks, it leaks at a roof penetration. It does not leak in the middle of a field of shingles or tiles. A skylight is a big roof penetration. As such, a skylight has the potential to leak. The difference between a skylight that leaks and one that does not is a good installer. A good installer knows how to pick a good skylight and knows how to flash the skylight properly so it sheds water.


There two types of skylights commonly used for residential homes. Skylights that have to be mounted on a curb and a skylight that comes with its own curb (integrated curb). The best is the type that mounts on a curb. A curb mount skylight sits up above the roof plane on a wood frame. A curb mount skylight gets flashed just like a chimney. It gets step flashing, head and base flashing. The illustration below shows a curb mount and flashing for a skylight. All that is required is to set the skylight on the curb.

Peel and stick ice and water shield have made skylight installations much more reliable. Most installers use ice and water shield to compliment the skylight flashing for a good water-tight installation in any weather conditions.

# Signs of Trouble

Once a skylight is installed, it may be difficult to recognize if the installation was done properly. Here are a few signs that there could be trouble -

- Mastic or sealant (roofing tar) has been used to seal the skylight. Good skylight flashing should shed water and does not require mastic. Mastic on the flashing is a sign of trouble.
- If a skylight is installed too close to a plumbing stack or some other roof penetration or intersection (less than 18 inches) it is very difficult to flash properly. Room is needed around the skylight for the flashing components.
- Moisture or stains on the inside could be evidence of a leak or could be condensation. Sometimes it's hard to determine what you are looking at.



This illustration shows a curb mount for a skylight, shown without the skylight for clarity. You can see the step flashing and the apron flashing.

Pillar To Post®, the home of home inspection

We welcome your comments and suggestions for future Information Series topicsinfo@pillartopost.com1-800-294-5591www.pillartopost.com